Items that Remain to be completed (05/22/15):

1. Main Warehouse

Floor Sweepings: Pick up Floor Sweepings Cleanup: Final Cleanup of Bays and Area

2. Aboveground Storage Tank Area

Residual Sludge: NT8, NT2

South Containment: Final Cleanup and Boom around tanks

Piping: Evaluate Piping to See if Additional Actions Required to Remove Materials

3. Frac Tanks:

Frac Tanks 5180/FT1001: Residual Sediment Cleanout Frac Tank FT1004: Pick up from TIBM along with drums

4. Dirty Totes (2): Cut up and put in US Ecology Box (OT25337

5. PPE: Put PPE into US Ecology Box (OT25337) – may need another roll-off?

6. Parking Lot: Pressure wash clean oily spot area

7. Stormwater Drains:

South Drain: Check after rainfall North Drain: Check after rainfall Pump Water if necessary

8. Waste Sampling/Disposal:

Frac Tanks: FT1001 (Needs Sampling) Roll-Off: OT25480 (Needs Sampling) Roll-Off: OT25337 (US Ecology – 5/28) Vac Box: VB25229 (Needs Sampling)

FT1004 Drums: TCEQ Disposal (Veolia Profile 678291)